

Electrical (5)

- cleaning energized 4160/480 volt transformer compartment
- checking water pump, which had reverse polarity on extension cord to pump, causing the motor housing to be energized
- while testing with meter, contacted improperly mounted circuit breaker hardware and an energized phase terminal
- contacted hand-held wand on a high-pressure washer, which had one phase wired directly to ground
- raised bed of over-the-road haul truck contacted 26kva power line and passenger was electrocuted while attempting to get out of truck